

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME..... "MERSEY ENGINEER"..... REPORT..... Liv. No. 157718

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features, in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey..... Docking: Repairs including <sup>When due</sup> part of the conditions of class.

NOTED.

SUBJECT to side shell plating being specially examined and dealt with as necessary at the Special Survey.

IN S.R.L. APPENDIX.

Shell plating etc. (p & s) indented.

Bulwark plating etc. set in and buckled.

DB/PT.  
22. 11. 61.



© 2020

Lloyd's Register  
Foundation

005293-005300-0205