

Attached fuel injection pumps and LP fuel pump
Attached lubricating oil service pump

of Surveyors.....

Received from Chief Surveyors

20 MAR 1945

NAME "POZARICA"

REPORT

Bal.

8113

Grk.

No 22928

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION

When due

The machinery of this vessel was not built under Special Survey but the plans were approved prior to the war.

The machinery is being surveyed for Classification on the Continuous Survey basis and the greater part has been opened out and examined by the Baltimore Surveyors and found in a satisfactory condition; only minor repairs being necessary.

It is submitted that this vessel is eligible for the record DBS 12.44, S.10.44 as assigned by the American Committee.

Note 2 DB(WT) 180 lbs. CL



Recd. 19.3.45

© 2021
Lloyd's Register
Foundation

005301-005306-0033

(T.O.)

sent upon it