

COPY.

654953

Lloyd's Register of Shipping.



Port GLASGOW.

27th April, 1946.

This is to Certify that

J. H. STEELE.

the undersigned Surveyor to this Society did at the request of Messrs. Stewarts & Lloyds, Ltd., attend at their Coatbridge Works on the 14th December, 1945, and subsequent dates for the purpose of selecting and witnessing material tests of tubes and fittings for 9 derricks as detailed on attached signed advice note.

These derricks which are to the order of Messrs. Cammell Laird & Co. Ltd., Birkenhead, and intended for Order No. R.92861/SR of 21st November, 1945, Job "HILARY", were finally inspected and subjected to axial compression tests on the 24th April, 1946, with satisfactory results.


The materials have been manufactured in accordance with the requirements of the Society's Rules.

Derricks stamped: J.H.S.

Surveyor to Lloyd's Register.

FEE: £8:8:0d.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed and it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Members or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



ARY"

RECOMMENDED

castle and main decks
ing.

Decks to be searched and caulked.

on forecastle broken
stay bent.

Rail to be welded in place and
stay straightened and refitted.

breast No.2 hatch
board side bent.

To be straightened and refitted.

motor pipe casing after
of promenade deck damaged.

To be partly renewed.

peak hand pump covering
e damaged.

To repair.

castle fire hose box
lft.

To be refitted.

light and fittings
aged.

To be renewed.

blackout screens
aged.

To be repaired and refitted.

mess and lavatory
floors for same destroyed.

To be renewed complete.

end of after gun platform
destroyed.

Platform to be renewed as
necessary together with distorted
beams, brackets and clips.

bell and telephone
aged.

To be renewed.

guide for Paravane A
broken.

New link to be fitted.

Surveyor to Lloyd's Register of Shipping

& Exps. \$54.00



© 2021

Lloyd's Register
Foundation

005307003160077

74

77

Certificate in
the Comm
it is to be
to be held
the Register
or any M

2011.10