

if situated near unprotected woodwork or other combustible material, state distance of same horizontally from on

W. Sc. Martua.

Rot. 13523.

Before this Case receives consideration it is submitted that the Report be returned to the Rotterdam Surveyors who should be requested to fill the required particulars of the lighting conductors which have been omitted from Report.

J.M.
24/5/24,

Lloyd's Register
Foundation

005307-005310-0138

bars yes, individual fuses to voltmeter, pilot or earth lamp yes, connections of s

Main Switchgear. description of switchgear for each generator and each outgoing circuit and arrangement of equalizer switches