

H. EFSTATHIOU
Engineering Works.

Alexandria 3rd. November, 1945.

S.S. "TOKAR"

List of repairs carried out on board the above named steamer,
to this day:-

DECK REPAIRS:-

Renewing several plate on centre aft deck.
Renewing aft peak top tank plates.
Forward deck plates, partly renewed.
Renewing approx. 75% of cross bunker bulkhead plates.
Renewing approx. 75% of centre ship's hull plates.
Renewing approx. 75% of forepeak bulkhead plates.

BOILER REPAIRS.

Overhauling all boiler mountings.

ENGINE ROOM REPAIRS:-

Engine generally overhauled.
Skimming H.P. and L.P. cylinders.
Skimming H.P. slide valve cylinder.
Adjusting L.P. slide valve's face.
Skimming crank shaft.
New white metal casted on bearings.
Skimming connecting rods.
Skimming thrust shaft.
Adjusting motion links as necessary.



© 2021

Lloyd's Register
Foundation

005311-005317-0169