

Rpt. 8

Date of writing Report 14/12/57 When handed in at Local Office 14/12/57 Received London 30 DEC 1957  
Survey held at SYDNEY N.S.W. No. of Visits 3 First Date 6/11/1957 Last Date 6/12/1957

# REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B. 26778 on the Iron or Steel S.S. Steel Screw Tug "ST HILIARY" Tons gross 390  
Built at Lytham By Whom Lytham S.B. & E. Co. Ltd., Year 1919 Month 11  
Owners Waratah Tug & Salvage Co. Pty. Ltd. Owner's address (If not already in R.B.) Newcastle N.S.W.  
Managers - - - - - Port of Registry  
Surveyed Afloat or in Drydock Both Name of Dock Chapmans floating dock Date of last examn. in Drydock 2.12.57  
N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.  
Last Report: No. 1851 Port NSW  
To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr.). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS	Machinery
Date of Special and of Drydocking Surveys, etc.	
+A1	+LMC 8,54
for towing purposes	B.S. 9,56
9,56	T.S. 7,540G
SS NSW 8,55	

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined. Freeboard as marked on ship and now verified ft. ins.  
Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR Annual Dry Docking & Repairs.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? Yes  
If so, is the Report sent now, or when will it be sent? Now  
Is Classification Certificate required? If so, to be sent to  
Has Interim Certificate been issued? Yes

## GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this Survey, for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. 1,55".

This vessel as far as seen is now in good condition, eligible in my opinion to remain as classed and to have the Record of Dry Docking 12,57 made in the Register Book.

E.G. Hughes  
Surveyor to Lloyd's Register of Shipping  
(E.G. Hughes.)

Date of Committee

TUESDAY 18 FEB 1958

Minute

Ds 12,57

TS 12,57 MBS 12,57



PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR

Rpt.

## Surveyed

for Ar  
and th  
Register  
recomme  
that I

The present condition of the following parts in so far as examined is to be reported:—

being fr

This Certificate  
"While the C  
erly executed,  
circumstances  
a Surveyors, on  
ult or negligenc  
Society."

B. Copy) 4M-1/5

B. Copy) 4M-1/5

Second Surveyor's Fee (if any)

Date when A/c. Rendered ..... 16/12/57

Date when A/c. Rendered ..... 16/12/57

© 2020

(if any) \_\_\_\_\_  
\_\_\_\_\_ 16/12/ 57  
\_\_\_\_\_  
\_\_\_\_\_