

-8 DEC 1964

Ship's name BRITISH CROWN

Port Nwe.

No. 1577

Class is subject to :-

Last survey date 22-10-64

1. Propeller and outside fastenings being specially examined at the next drydocking.

Docking:- Wear down $\frac{1}{5/32}$

Subject Item 1:- Now examined and found satisfactory. The

Surveyor recommends that this Condition of Class be deleted.

MBS:- Due $9/64$, now held.

CSM:- Due $9/64$, now completed.

The Surveyor reports renewal of the port main boiler superheater elements and support plates, subsequently tested. Both main turbine rotors have been repaired as necessary where blading was defective and a number of minor repairs carried out.

It is submitted that this vessel is eligible for THE RECORD. CSM $10/64$ and MBS $10/64$ without Subject.

(unr)
The Surveyor should be asked to arrange the examination of the aux. starting air pipes early in the new CSM cycle and [to inform us if external de-super heaters are fitted].

End. E.2/

CERTIFICATE WRITTEN

005337-005343-0057

10/12