

COPY

Rpt. C. 11 (Contd.)

Index No. 28895

Lloyd's Register of Shipping.

Ship's Name "PRONTO"

Official No. 6278

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in _____

Hatchways : -

Upper Deck. Bunker hatches, 1 p. 1 s. abreast No.3 main hatch, now removed and openings permanently closed.

Side bunker hatches, 1 p. 1 s., now removed and openings permanently closed.

Main Deck. Bunker hatch now removed and opening permanently closed.

Bunker hatches, 1 p. 1 s., abreast No.3 hatch, now removed and openings permanently closed.

Cargo Port Doors now permanently closed.

Ventilators : -

Upper Deck. One 12" dia. ventilator, abaft No.3 hatch, removed and opening permanently closed.

Air Pipes : -

Upper Deck. Four air pipes, 2 p. 2 s., fitted to new cofferdams. Pipes 2½" dia. opg. 18" above deck.

Four air pipes, 2 p. 2 s., fitted to No.2 & 3 D.B. tanks. Pipes 4" dia. opg. 18" above deck.

Six air pipes, 3p. 3 s., fitted to cross bunkers and settling tanks. Pipes 3½" dia. ogs. 18" above deck.

All air pipes fitted with gauze wire and approved covers.

James L. Anderson
Surveyor to Lloyd's Register

HONG KONG.

26th December, 1951.

AA
25 JAN 1952



© 2021

Lloyd's Register
Foundation

005358-005366-0210