

CHARLTON STAR (EX. EMPIRE BURE) Report ANTINERP No. 28 OCT 1950

ESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in DECIMALS of an inch.

	AMIDSHIP.				FORWARD.				AFT.				REMARKS.		
	Original Thickness.		Thickness by drilling.		Diminution if any.		Original Thickness.		Thickness by drilling.		Diminution if any.				
	Port.	Std.	Port.	Std.	Port.	Std.	Port.	Std.	Port.	Std.	Port.	Std.			
SHOES MAKE.							42	40	38	02	04				N O = PLATING RENEWED.
										40	40	40	-	-	
N	80	96	92	-	-	46	58	56	-	-	46	46	45	-	01
M	70	67	66	03	04	46	52	51	-	-	46	49	48	-	-
L	68	34	61	34	07	46	50	50	-	-	46	54	47	-	-
K	68	34	34	34	34	46	54	51	-	-	46	42	50	04	-
J	68	35	68	33	-	46	40	44	06	02	46	42	44	04	02
H	68	53	45	15	23	46	42	40	04	06	68	46	46	SEE	NOTE:- DRILLED IN WAY OF A.P. BULK <sup>d</sup> ORIGINAL THICKNESS .48"
G	68	54	52	14	16	46	56	44	-	02	68	64	50	NOTE	
F	68	60	68	08	-	50	48	48	02	02	68	80	72	-	-
E	68	CEMENT.				50	STEALER			-	68	70	68	-	-
D	68	-	"	-	-	50	68	70	-	-	68	70	68	-	-
C	70	-	"	-	-	70	STEALER			-	70	69	66	01	04
B	70	-	"	-	-	70	65	64	05	06	70	52	54	18	16
A	72	-	"	-	-	72	CEMENT			-	72	CEMENT			

fall favor.

1.08 - " -

85 CEMENT  
Drillings at ends to be made in the vicinity of the peak bulkheads.

005377 - 005386 - 0184

GOOD

Have Watertight Doors been examined and found efficient? YES.

Transoms, Pointers & Crutches