

4E

subject to

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor 16 MAR 1961

S NAME.....

"VILLANDRY"

(REPORT 8)	DNK	5015.
REPORT (REPORT 9)	DNK	No. 5015.
	MSL	12978.

CS advanced.

The Surveyor reports some repairs effected to the brickworks of the port boiler, also the Surveyor reports the port cylinder crosshead guide seating of the windlass found broken and some temporary repairs effected by fitting a welded steel piece in place of the seating and the Surveyor recommends that the class be made subject to the port cylinder block of the windlass being renewed before the end of June, 1961.

IT IS SUBMITTED that this vessel is eligible to remain as classed subject as recommended.

NOTE.

Ship Reports to note.

© 2021
 Lloyd's Register
 Foundation

005377.00 5386.0278