

COPY

# LLOYD'S REGISTER OF SHIPPING

D 50



Port D J A K A R T A

7th February 1959,

This is to Certify that

J.A. Boater

the undersigned Surveyor to this Society did at the request of Messrs. P.T. Johs Larsen & Co, (Indonesia) Ltd, Djakarta, Agents for the Owner's the Indian and Pacific Ocean Merchants Ltd, Hong Kong, and with the consent of the Charterers N.V. Djakarta Lloyd, Djakarta, attend on board the:

s.s. "WILLIAM CHARLICK 4", 4259 Tons Gross of Hong Kong,

on the 2nd February 1959, whilst afloat at Tandjong Priok for the purpose of carrying out a re-delivery Survey. The vessel being re-delivered by N.V. Djakarta Lloyd to Messrs. P.T. Johs Larsen and Co (Indobesia) Ltd, on behalf of the Owners.

It was agreed by the Charterers and Owners Representative that the following wood hatch covers (on the weatherdeck), stated to have been damaged during the Charter period, be renewed:-

No. 1 Hatch

4 - 4 ft. wood covers, 1-9 ft. wood cover

No. 2 Hatch

6 - 9 ft. wood covers.

No. 3 Hatch

2 - 5 ft. wood covers

No. 4 Hatch

4 - 9 ft. wood covers

No. 5 Hatch

10 - 9 ft. wood covers.

J.B.

.....Contd.....

certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-  
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



It was also agreed by the Charterers and Owners Representative that at 13.30 on the 2nd February 1959 the following quantities of oil, coal and water were on board:-

Oil fuel bunkers	408.2 Tons
Galley coal	3.0 Tons
Boiler water	78.0 Tons
Domestic water	207.0 Tons

J.A. Boater

(J.A. Boater).



© 2020

Lloyd's Register  
Foundation

0011 2/2