

W O K I N G H A M C O P Y

"EMPIRE STOUR"

Built 1930. Classed #100A1.

After damage through ~~grounding~~, enemy action and subsequent grounding extensive repairs were effected and a Reclassification Survey No.3 ~~was~~ held 12.41.

The reports have been carefully examined and as regards damage from heavy weather and structural defects there is nothing abnormal to be noted.

No objection is, therefore, seen to the Endorsement of the Certificate for Deeper Loading.



©

2020

27.8.42

NSW 82-B
Lloyd's Register
Foundation

005387-005396-0239

Chief Supt. Engineer.