

as per Rule
Screw Shaft, diameter as fitted... 1 7/8" ✓
Is the (tube) screw shaft fitted with

REGISTER NEWCASTLE

TELEPHONE: 21391 (3 LINES)



RECEIVED
Lloyd's Register of Shipping,

18 FEB 1949

AN80

Collingwood Buildings, Newcastle-on-Tyne, 1.

16th February, 1949.

Reference The Secretary,
London.


Dear Sir,

M.V. "PALUDINA". NEWCASTLE-ON-TYNE, No. 105889

With reference to the Generator Test Certificates for the above vessel, application for these certificates was made to Messrs. Swan Hunter & Wigham Richardson Ltd. on 18th November, 1948. Owing to fire in the electrical drawing office of this firm all records have been lost. Further application for certificates has been made and these will be forwarded as soon as possible.

We are, Dear Sir,
Yours faithfully,
THE SURVEYORS.

per




J. C. Wright

Lloyd's Register
Foundation

005397-005402-0012

efficiently high on the ship's side to be seen without lifting the platform plates. I.C.S. Are the overboard discharges above or

Referred to the D.O.

A handwritten signature in black ink, consisting of a large, stylized 'R' followed by a loop and a tail that ends in a small arrowhead pointing downwards and to the left.

For Engineer Surveyors (F.E. Rpts.) to note.



© 2021

Lloyd's Register
Foundation