

Chief Surveyors

Received from Chief Surveyors

SHIP'S NAME *Steel S. ARMADALE*

Report

*Gls*

No. *49652*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/52.)

re of Survey

*1<sup>st</sup> Entry*

When due

*Revised Rules.*


*+ 100 A-1 (Steel) with Freeboard.*

*2 D<sup>45</sup> (Lcl) + Shelter D<sup>4</sup> (Lcl)*

*FK. Suct Keel forward of Mch Space. 7 BH (all BH to Shelter D<sup>4</sup>, 6 BH to 2<sup>nd</sup> D<sup>4</sup>)*

*ht Cem Loads A & CP*

*Cell DB 346' 1086t MT 34' 1025t FRT 98t APT 111t*



© 2021

*WDA*

*3-10-29*

Lloyd's Register  
Foundation

005397-005402-0028

005397-005402-0029

Are Frame and Reversed Frame  
joggled ?.....

*72*