

COPY

EA
Ship's name "LABIOSA"

Port

CCO

No. 6673

Last survey date 16.1.63.

Class is subject to

set up keel plate in way of forward cofferdam being specially examined and dealt with as necessary by the Special Survey and to indented side shell plating etc. in way of No.3 wing tank (p.s) being dealt with as necessary at the next drydocking.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Docking: ~~Temporary~~ repairs to damage (cause not stated).
Examination of deferred items as above.

PERMANENT

Recommendation

SUBMITTED record of DS 1,63be assigned, subject as above.


DS 1,63 Subject.

INTS. R. L. APPENDIX.

Shell plate F.4 (p.s.f) indented.
Keel plate forward set up.

NOTE: It would appear from this report that the Owners intend to lay up or scrap the ship in 4,63.

© 2020



Lloyd's Register
Foundation

005429-005435-0014