

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

19th September, 1963

Dear Sir,

CLASSING LETTER


C
RLT/RW

572 "COLWYN BAY". As recommended, and subject as previously recorded. The rivets in the boiler shell seams should not be over welded and, where repairs of the nature now reported on are carried out to the boiler seams, the class of the vessel should be made subject to the repairs being re-examined on arrival at the home port on completion of fishing voyage.

Yours faithfully,

pro Clerk to the
Classification Committee

V.R. Jessen, Esq.,
REYKJAVIK



© 2020

Lloyd's Register
Foundation

005429-005435-0113