

Chief Surveyors

Received from Chief Surveyors

SHIP NAME

EMPIRE AIRMAN

Report Liv

No. 117603

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)


Survey

Damage

~~When this~~

Subject to set down f'cle deck plating and indented shell plating (p & s.f) being permanently repaired at the first convenient opportunity, to top of sternframe, E.W. & reinforced ⁴42, being specially examined at the next dry docking and to (a bower anchor and 60 fathoms of chain cable being supplied).

(H.W.)



© 2020

Lloyd's Register
Foundation



005436-005442-0176