

750,12,27.

FREEBOARD REPORT on the

S.S. "Comedian".

It is submitted the Freeboards given on the accompanying form, being those required by the Tables, merit approval.

The Surveyor should confirm there are only 5 Hatch Web Plates in No 4 Hatchway instead of 6 as fitted in sister vessels.

S.W.B.

26-8-29.

2 plans to return *N^o 26.8.29*

26.8.29



© 2021

Lloyd's Register
Foundation

005453-005461-0184

Name of Broker or Agent