

L.S.Ts Nos. 3004 and 3018.

IT IS SUBMITTED the Surveyors be informed that owing to the shell plating being thinner than required by the Rules and to the scantlings being generally lighter it is not possible to recommend the vessels for the 100A- class.

If the Figure 1 is desired the equipment should be in accordance with the letter "v" Table 53 of the Rules, provided the erections are similar to those contemplated for the original construction of the vessels.

23th July, 1947.



Lloyd's Register  
Foundation

005453-005461-0216