

summary
should be
respectin
damage

28 APR 1942

Received from Chief Ship Surveyor _____

Inspected by Chief Ship Surveyor _____

VESSEL'S NAME SINGKEP Rpt. Sba _____ No. 4521

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey DOCKING

Notations of 100A1 (Class contemplated) and 'Examined 6,41' valid for 12 months, have been assigned to this Dutch vessel.

The case is fully stated in Endorsement dated 21.10.41.

The SOURABAYA Surveyors report this vessel placed in dry dock, bottom and rudder cleaned and coated.

The Surveyors recommend starboard after sanitary discharge be renewed at the first opportunity.

It is submitted her records in the Register Book be maintained.

(Docking date 1,42)

LR © 2020
Lloyd's Register
Foundation
025462-000464-189
8.4.42
latih

Inner Bottom