

S/S Lagomar Gun Rpt 3311

Submitted before dealing with this case

the ^{Grimby} Surveyor should be requested to

state "when the stern tube propeller, screw shaft
& all connections were examined in dry dock."

also if "the discharge pipes are above or below
deep water line" as this is omitted from Rpt

* quoted from Rpt Entry

Sal.

H.S.

27.10.04

27.10.04

005470-005479-0092

Material	Diameter	Length	Thickness of shell plates	Material	Description