

1

Sent to Chief Surveyors 18/6/12

Received from Chief Surveyors _____

VESSEL'S NAME 'H S Skulda'

Report hon

No. 75007^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 2A/6/92.)

Nature of Survey Damage

When due _____

This vessel was recently reported by the Newcastle Surveyors to have sustained some ~~serious~~ damage to three shell plates and two frames through striking a pier at Hull. Temporary repairs were effected to their satisfaction, and it was stated that permanent repairs would be carried out at the next dry docking, but that the Owner did not desire to continue the classification of the Vessel.

The Owner now states in reply to inquiry that he does not intend to continue the classification of the Vessel in the Society's Register.

It is submitted the vessel's class be withdrawn from the Register Book, and three dots inserted in lieu thereof indicating withdrawal of class at Owners' request.

Withdraw Class
Insert (...)

FRS

M. R. 1377

E. C. L.



© 2020
8/6/12

Lloyd's Register
Foundation