

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

9th October, 1936.

Dear Sirs,

H. With reference to your report No. 14475 on the Motorship "CABO SAN AGUSTIN", I have to acquaint you I am informed by the Society's Surveyor at Barcelona that he has been informed by the Owners' Representative that owing to the vessel being partly loaded the Special Survey No. 1 could not be completed at that port, but that the vessel will leave Barcelona for Genoa as soon as existing circumstances permit where surveys and repairs will be dealt with.

In the circumstances consideration of the case has been deferred by the Committee for a short time and I shall be glad if you will be guided accordingly.

I may add that ⁱⁿ August last the Society's Surveyors at Buenos Aires reported that the vessel had been examined afloat and on account of damage through fire in No. 3 shelter deck some deck plating was found buckled. Temporary repairs were effected but the Surveyors recommended that in view of the slight/damage, nature of the repairs to No. 3 shelter deck plating, beams and after bulkhead of the No. 3 shelter deck tween decks be effected at the first convenient opportunity.

I am, Dear Sirs,
Yours faithfully,

The Surveyors,

Lloyd's Register
Foundation

6510-875508-8159