

REGISTER. BILBAO.

Lloyd's Register of Shipping.

OFICINA PRINCIPAL: FENCHURCH STREET, 71, LONDRES, E.C.3.

Calle de Ibañez de Bilbao No. 22,
4th Storey
(Apartado 286),

LLOYD'S REGISTER
RECEIVED
12 SEP 1931
Ansd. X
LONDON

Bilbao, 9th September, 1931

DRES:
ORD.
AZA.
HALL.
ULLARD.

Dear Sir,

M.V. "CABO SAN AGUSTIN"

Messrs. S.E.C.N. Hull No. 53

With reference to your letter of the 5th instant, regarding the above vessel we have to inform you that owing to the lack of facilities at the floating dock at which this vessel was dry-docked at Bordeaux the submarine signalling apparatus was not fitted.

We may add that the builders intend fitting this apparatus at Genoa at the next drydocking, and the Genoa Surveyors are being informed accordingly.

We are, Dear Sir,

Yours faithfully,

R Crawford
For the Surveyors

The Secretary,
LONDON.



© 2020

Lloyd's Register

Foundation

005518-005528-0184

Refer to the Chief Surveyor

Department of the Secretary

Referred to the Chief Ship Surveyor.

12 SEP 1931

Also for Mr. S. A. Hill to note.

LONDON,
The Secretariat.

For the Surveyor
Yours faithfully,
[Signature]

Dear Sir,

being informed accordingly.

at Genoa at the next drydocking, and the Genoa Salvage Co are

We may add that the builders intend fitting this apparatus
was not fitted.
was dry-docked at Bordeaux the submarine signalling apparatus
the rack of facilities at the floating dock at which this vessel
regarding the above vessel we have to inform you that owing to

With reference to your letter of the 27th instant,
Messrs. S. E. C. M. Hill No. 38
N. Y. "CUBO SAN VINCENZI"

Dear Sir,

Bilbao, 27th September, 1931
(4880 580)

4th Street

Calle de Irujes de Bilbao No. 55,

OFICINA PRINCIPAL: BARRIO DE SARRIENA, AT. GOARDIA, E.C.3.

London & Registrar of Shipping

© 2020 Lloyd's Register Foundation

TELEFONO 18120

REGISTRAR GENERAL