

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

12th June, 1934.

Dear Sir,

With reference to Hamburg Report No.21161 on the machinery of the M.V. "CARIPITENO", I have to draw the Surveyors' attention to the following extract from my letter of the 8th October, 1930, addressed to Mr. Dykes at Danzig, viz:-

"I have to point out that as the N.H.P is above 70, "either two bilge pumps worked from the main engines "or an additional independent power pump should be "connected to the main bilge line".

It would appear from the Surveyors' report that only two bilge pumps are fitted, viz:- one on the main engines and one independent, and I shall be glad if they will state what further provision has been made to comply with the above requirement.

I am, Dear Sir,

Yours faithfully,

A. Chisholm Esq.,
HAMBURG.

Secretary.

© 2020



Lloyd's Register
Foundation

005524-005536-0100