

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor 16.3.23

VESSEL'S NAME Stl. M.V. "CRISTO" Rpt. Lon. No86441

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor

The class of this vessel is subject to the inner surface of the bottom plating being examined in twelve months from the 15th August, 1921.

A proposal to defer the examination of the inner surface of the bottom plating for two months from the 11th December last was agreed to.

The London Surveyors now report vessel placed in dry dock, bottom and rudder cleaned and coated; and a number of rivets in the bottom renewed and the caulking overhauled, the ceiling lifted and the inner surface of the bottom plating examined and found in good order.

A few plates in the bottom were found to be set up, damaged through grounding, and the counter plating damaged, and the Surveyors recommend that the damaged plating be dealt with at the Owners' convenience, and the inner ^{Surface} service of the bottom plating be again examined before April, 1924.

It is submitted the vessel appears worthy to remain as classed with record of survey, subject as recommended.

100A-1 } subject
3.23 La }

M.
15.3.23.



© 2020

Lloyd's Register Foundation