

24 FEB 1942

Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

NAME.....CHILTERN.....Rpt.....Cff.....No.....54161

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

A S.S. No.2 became due 8.41 (vessel 25 years old).

The CARDIFF Surveyors report the vessel placed in dry dock & bottom coated, & minor repairs effected.

This vessel has been requisitioned by the Admiralty & converted for Special Service.

It is submitted the vessel appears worthy to remain as classed and to have record of docking 2.42.

2.42. Cff.

b. 2.42
20.2.42

PLATING to be DRILLED when vessel is 24 years old, or at next Special Survey thereafter.



© 2020

Lloyd's Register
Foundation

005618-005634-0043