

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19 When handed in at Local Office 19 Port of Melbourne

No. in Survey held at Date, First Survey Last Survey 19

Reg. Book. 542 on the Wood, Iron or Steel Twin Sc. Ctr. "Pioneer" Master W. Johnston

TONNAGE:—

GROSS 542

UNDER DECK 498

NET 192

Built at Glasgow

By whom Ferguson Bros

When 1905 - 5

Owners Agent General for the State of Victoria Port belonging to London

Owners' Address

(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 14286 Port Gnk

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey, Date of last Survey and of Periodical Surveys.	Years Assigned Surveyed	Machinery and Boiler Surveys (including rate of N.B., if any).
+ A1		+ LMC
Hopper dredger for River purposes.		4.05
5.05		water tube Boilers

Society's Freeboard (if assigned) as painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired ...								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE	Stringers	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	(State which.)	Caulking ditto	Sails
Rivets	Rudder	Treenails ditto	Equipment letter
Breasthooks & Crutches	Steering gear and its connections	Breasthooks & Stemson ditto	Anchors, No. of
Transoms	Windlass	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Pumps now been examined and found efficient?	Timbers of Frame at openings ditto	„ length size
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Ditto ditto at other places ditto	„ Rule length size
Floors	Have Watertight Doors now been examined and found efficient?	Stringers, Clamps & Shells ditto	(per Table 22)
Keelsons		Salting ditto	Hawser & Warps
		(State if examined.)	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey, 1,07,” or “to remain as classed and to have record of survey, 1,07, and the notations of ss No. 1-07 and ptND07, &c.”

Survey Fee (per Section 28)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 28)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

FRI. 25 SEP 1908

Character Assigned

omit class on reprint of R.B.

Lloyd's Register

005618-005634-0213



Lloyd's Register Foundation