

Is there a drain arrangement fitted at the lowest part of each receiver

Humboldt-Deutschstein { 502489
496725

Quasidorof Rpt: 236.

Quasidorof Surveys should be referred to the Secretary's letter E dated 5.10.37
should be requested to say if he is correct in stating that the BHP is 8
and the revolutions per minute 1250.

Utami Rpt. pending reply to above.



20. 6/4/38 2020

Lloyd's Register
Foundation

005618-005634-0332

SPARE GEAR As per Rules.