

Tom
s.s. "Quitador" .

5 MAR 1930


The modified survey of the oil engines became due in December last.

In reply to enquiry the Buenos Aires Surveyors have forwarded a letter from the Owners in which they state that as the vessel works only in the river, they do not intend to continue the classification.


IT IS SUBMITTED the vessel's class be withdrawn from the Register Book and three dots inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...



7. 3. 30.



© 2021

Lloyd's Register
Foundation

005635-005643-0011