

Walter Jennings

The class of this vessel has been withdrawn
(...) inserted. Can. M. 2.6.44

It is submitted records of preboard and
sought be deleted from the Register Book.



JPS
© 2021
1-6 JUN 1944

Lloyd's Register
Foundation

005635-005643-0153

the shelter tween decks port side, it should be provided with a screw-down, automatic, non-return valve.

You should satisfy yourselves with the efficiency of the arrangements, particularly the appliances for closing hatchways and other openings in the shelter deck.

You should report full particulars of the alterations carried out on a Rpt.C11(Contd), placing a copy on board the ship. You should also give full particulars of the closing appliances of the openings in the forecastle bulkhead.



© 2021

Lloyd's Register
Foundation