

Chief Surveyors

Received from Chief Surveyors

NAME Stl S "ROBERT HOBSON Report clv No. 378

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

of Survey

1st Entry

When due

✱ 100A.1. (Steel) " For Service on the Great Lakes
 1 D¹ (Stl) + Web Frames. " Longitudinal framing at bottom and at deck
 Cell D.B + E + B. 56' 242t. Cell D.B + Side tanks in way of holds 471' 7934t
 F.K, 3B.H, Lloyd A. CP F.P.T. 471t, A.P.T. 68t
 F48' machy aft.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

The Surveyor should be requested to forward the forging reports.
 It is concluded that 180 fathoms of chain cable has been supplied into the
 Surveyor should be requested to state if this is so.

005644-005655-0038