



Lloyd's Register of Shipping,

High Close,

Wokingham, Berks,

Fbd.

To the Surveyor(s) at HONG KONG.

Vessel's Name,

"HIN SANG"

12th August, 1941.

QUESTION.

With reference to your
Fpt. Cl2(b) and Cl1(contd.), I
have to inform you that it is
concluded that the double bottom
tanks within the midship half of
the ship have adequate longitud-
inal sub-division, and that
efficient provision has been
made for steering in the event
of a breakdown in the main steering
arrangements.

HEU

ANSWER.

Date:—

27th. November 1941.

All double bottom tanks except
No.1 & 5 have adequate longitudinal
subdivision.

This vessel has telemeter gear
from bridge to hydraulic gear in
poop also telemeter gear from poop
deck and hand gear from poop deck.

CR

*Noted
18/12/42*



© 2021

Lloyd's Register
Foundation

005656 - 005670 - 0254