

COPY.

HONG KONG.

"HIN SANG"

12th August, 1941.

With reference to your Rpt. C12(b) and C11(contd.), I have to inform you that it is concluded that the double bottom tanks within the midship half of the ship have adequate longitudinal sub-division, and that efficient provision has been made for steering in the event of a breakdown in the main steering arrangements.



© 2021

Lloyd's Register
Foundation

005656-005670-0258