

ARD REPORT on the


HIN LANG

It is Submitted the Hong Kong Surveyor has advised it is concluded that the double-bottom tanks within the midship half of the ship have adequate longitudinal subdivision and that efficient provision has been made for steering in the event of a break down in the main steering arrangements.

A.L.

11.8.41

S.B.

Lloyd's Register
Foundation

005656-005670-0259

fee paid?

Form for Certificate Hong Kong LL 215.