

total capacity tons. FPT tons; APT tons; MT feet (tons.)

All alterations in the existing records should be underlined.

CHARACTER.

2

Chief Ship Surveyor 16.7.14.

Received from Chief Ship Surveyor

SHIP NAME ^{Swan} Steel S.S. Bosphorus 7065

Rpt. Cpl

No. 2470

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Survey ¹² S.S. No. /

The ¹² S.S. No. / has now been held, and the following repairs done due to wear and tear:-

Bottom cleaned & coated.

A bower anchor & part of the cable have been put ashore and the Surveyor recommends figure I to be expunged.

It is submitted the vessel is worthy to remain as classed, ^{without the figure I and} with record of Survey 7.14. Cpl and notation of S.S. Cpl 70-1.14 as recommended.

A -

on the Bosphorus & sea of Marmora

7.14. Cpl.

S.S. Cpl. 70-1.14.

Expunge figure I



© 2021 Lloyd's Register Foundation

005671-005683-0181