



Lloyd's Register of Shipping,

49, Queen Square,

Bristol, March 17th, 1924.

LLOYD'S REGISTER
Recd. 18 MAR. 1924
Ans'd. 19
LONDON

Dear Sir,

Withreference to your letter of the 5th instant enclosing copy of a communication from the Owners of the S.S. "NORTHQUAY", regarding the electric light installation, which was fitted at Llanelly, but not examined, I have to state that an opportunity has been afforded in this district to examine the installation as far as possible in its completed condition, and several items of a more or less minor nature were placed before the Owners to be attended to, all of which have now been carried out with the exception of an automatic indicator which has to be fitted in connection with the navigation lights, and as the Owners do not desire to have this instrument fitted, I shall be glad to be informed what further action is to be taken in the matter.

The incomplete report is, in the meantime, being retained in this Office.

I am, Dear Sir,

Yours faithfully,

John H. Guinness
Lloyd's Register
Foundation

The Secretary, LONDON

005740-005755-0103

Referred to the Chief Engineer Surveyors.

18 MAR 1944

It is submitted that the Owners & District Surveyors be informed that in order to meet the requirements of the Rules Section 7, para. b. of the Rules for Electric fittings must be complied with.

Chs. 15.3.24

WRA



© 2020 Lloyd's Register Foundation