

veyors 11. 2. 24

12 FEB 1924

Received from Chief Surveyors

ME

Northquay

Report

No.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Electric light ~~When due~~ installations

The Owners of this vessel stated on the 23rd ultimo that the vessel had been fitted with an electric lighting installation & asked that this might be noted in the Register Book.

The Bristol Surveyors state that the installation has been examined under working conditions only & found satisfactory. The particulars of the wiring & fittings require to be examined & compared with the Rules of the Society & reported on.

It is submitted the Owners be informed how the case stands & asked to make arrangements for the completion of the examination & advise this office when & where it can be done.

W.D.
17/2/24
P.D.



© 2020

Lloyd's Register
Foundation

005740-005755-0113