

F.E.

Received by Chief Ship Surveyor

9/5/12

Received from Chief Ship Surveyor

VESSEL'S NAME

At S I "Settsu"

Rpt.

Hul

No 24970

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

33.86

Depth "d"

11.17

Framing: Table No.

3 page 9

Description

Single angle as

Longitudinal No.

4063

approved.

Proportions

Length

9.6

Depth

Deck Sheerstrake

50 in less of 34

The 3rd anchor is 6 lbs less in weight than required, but the weight of the 1st anchor is 28 lbs in excess of that required.

In the report This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100 A.1. (Club) 'Steam Trawler' as recommended.

\pm 100 A.1 (Club) 'Steam Trawler'

1st Dr.

BK 7 $\frac{1}{2}$ 3 B.H. Gen. Lloyd's 2060 Q 7 $\frac{1}{2}$ F 20



© 2020

Lloyd's Register
Foundation