

S. S. Royalite

Tto 188.

Submitted the surveyor be informed that from the first entry report it does not appear that a donkey boiler was fitted, she should be requested to forward particulars of this boiler on a first-entry report form, together with a plan of same <sup>if possible</sup> for the consideration of the Committee also the date of build & name of the manufacturer

S.S.  
11/5/22. *Ans*

Re 16/5/22



© 2020

Lloyd's Register  
Foundation

005756-005778-0020

Strengthening rings (3x3x2 1/2) have been fitted