

Bronze Liners, thickness in way of bushes

as per Rule

Thickness between bushes

as per Rule

Is the after end of the

Engine
Boiler

No. 644 Made by Robbra (1931) Ltd.

For R. Dunstan Ltd. T. 413

Spwich Report No. 1115-44

It is submitted that ~~a copy of~~ this Report be
forwarded to the Hull Surveyors for their
~~returned~~ guidance and for completion.

Date



L.F.
25/11/63

© 2020

Lloyd's Register
Foundation

005756-005778-0148

Im 10.40.

MAIN BOILERS