

1

Sent to Chief Surveyors

24/10/12

Received from Chief Surveyors

VESSEL'S NAME

H Lightship Bull

Report

Don

No.

75055

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

Withdrawal of class.

The Owners representative states that this Lightship is undergoing repairs, but it is not intended to continue her classification with this Society.

It is submitted the vessel's class be withdrawn from the Register Book, and three dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class

Insert (...)

24. 10. 12.

© 2021

C. E. L. S.

P. R. H.

Lloyd's Register
Foundation

005774-005790-0251