

Port of HULL,
31st. May. 19 21.

REPORT ON MASTS, SPARS, AND RIGGING.

Gentlemen,

Having, in accordance with your instructions, examined
the Masts, Spars, and Rigging, and Iron Work of same, of the
S. S. "GERA".

I have to report that I found Wire seizings on lower splice of all
shrouds, stays, and backstays (in poor condition) to renew.

All derrick heel bolts (rust bound) to remove and make
workable and goose necks to free.

No mast wedges.

With the above exceptions everything is satisfactory.

William Broughton

Fee £ - : 10: -

To the Surveyors,
Lloyd's Register of Shipping,

HULL.



© 2020

Lloyd's Register
Foundation

005791-005810-0372