

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Survey held at Date, First Survey Last Survey  
Reg. Book. (No. of Visits)

Supp T 11646 on the Wood, Iron or Steel Sck Tiburon Master  
TONNAGE:- Built at Aberdeen By whom J. Guthrie Torry & Co When 1919

GROSS 246 Owners R de Baranza Port belonging to

UNDER DE. 244 Owners' Address  
NET 118 (not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; }  
total capacity tons. FPT tons; APT tons; MT feet tons. }  
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.  
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 12266 Port Am

CHARACTER.	Year Assigned	Machinery and Boiler Surveys
for Special Survey. Date of last Survey and of Periodical Surveys.	now assigned	(including date of N.B., if any).
+100A1 7.19 Stm Harlow		LMC 7.19

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired ...								
Fair'd or Repaired in place ...								

## PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt.)
Waterways	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Coamings	Ceiling	Scuppers	Boats
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	Rudder	Hatches	Condition, how ascertained
Caulking of ditto	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)
Rivets	Windlass	Caulking ditto	Sails
Breasthooks & Crutches	Have Pumps now been examined and found efficient?	Treenails ditto	Equipment letter
Transoms	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of
Frames	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Reverse Frames	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	„ length size
Floors		Ditto ditto at other places ditto	„ Rule length size
Keelsons		Stringers, Clamps & Shells ditto	Hawser & Warps
Stringers		Salting (State if examined.) ditto	Standing & Running Rigging
Inner Bottom Plating			

## General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey, 1,15,” or “to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c.”

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute

Character Assigned

Deferred for No. 1 to

Surveyor to Lloyd's Register of Shipping.  
TUE 11 DEC. 1923

Express class with a red line



Special General Committee

Thursday 13<sup>th</sup> December, 1923.

Classing Committee's  
decision confirmed

at

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

#### ANCHORS.

Number of Cables.	Anchors.*	WEIGHT EX STOCK.		WEIGHT OF STOCK.		TEST, PER CERTIFICATE.		WEIGHT REQUIRED BY RULE.		Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Owts.	qrs.	lbs.	Owts.	qrs.	lbs.	Owts.	qrs.			
	1st Bower ...											
	2nd "											
	3rd "											
	Collector's Weight.											
	Stream .....											
	Kedge.....											

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

#### CHAIN CABLES.

Number of Cables.	Length and size supplied.		Test per Certificate.		WEIGHT OF CHAIN CABLE.		Length and size per Rule.		Description.	Makers of Cables.	When and where tested and Superintendent.
	Length.	Diam.	Start- kory.	Break- ing.	Supplied.	Per Rule.	Length.	Diam.			
	Fathoms.	Ins.	Tons.	Tons.	Owts. qrs. lbs.	Owts. qrs. lbs.	Fathoms.	Ins.			

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2020

Lloyd's Register  
Foundation