

DISCLOSED  
BOX 40

SECTION.

93

F.E.

Received by Chief Ship Surveyor 25. 4. 05

Received from Chief Ship Surveyor

VESSEL'S NAME *St. Paddy's Bay "Riston"*Report *Nov* No. *48629*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

## CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .		
Spar Sheerstrake . .		
Description of Framing:— <i>Ordinary.</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

*The equipment is not in accordance with the requirements of the Rules.*

*In other respects* This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *For towing purposes* + 100 A — ("Steel"), as recommended.

*2/5*

+ 100 A — ("Steel") *"For towing purposes"*

*1 DR (10 sec)*

*BK 6" 3BH Cam.*

*C. H. J.*  
*25/4/05*



© 2020

Lloyd's Register  
Foundation

005929-005942-0104

50,44

Port  
Quarter, 'tween Deck, " " " "  
in Hold " " " "

WEB FRAMES, In Fore Body, No. and Spacing

Tie Plates . . .

Deck and

1/10 48 352