

Trawler "Rio Tejo"

Submitted the history Summary and informed he should notify the owner that if he desires this vessel's class retained in the Register. But an efficient watertight door to the Sumner's Satisfaction should be fitted to the opening in the bulkhead on frame No. 64 and the owner should be requested to state when and where this will be done.



© 2020

Lloyd's Register
Foundation

005929-005942-0130