

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 191... When handed in at Local Office 1921... Port of New York

No. in Reg. Book 28910 Survey held at on the Wood, Iron or Steel Date, First Survey S. S. "ROBIN GRAY" Last Survey 191

Master Skinner & Eddy Built at Seattle Wash By whom Skinner & Eddy When 1920 YEAR MONTH 1
Owners A S Shipping Board Port belonging to San Francisco
Owners' Address Robin Gray S.S. Co. Inc.
Tonnage: GROSS 6859 UNDER DK. 6531 NET 5120

Surveued Afloat or in Dry Dock? W B = Cell D Bor D Ba Name of Dock BAL Destined Voyage San Francisco

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER: + 100A1 Date of last Survey and of Periodical Surveys: 4 21 Machinery and Boiler Surveys (including date of N.B., if any): + LMC 1 20
Shelter dk w. fld TS (CI) 4 21
4 21 Fitted for Oil Fuel 1 20

Last Report, No. 3155 Port BAL
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.
Society's Freeboard (if assigned) as at above 150° Pa. painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR
See copy of letter dated 2nd September, 1921, received from the Seas Shipping Company, Inc. requesting the withdrawal from class.

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Fell.) When put on, Month Year
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Boats
Waterways	State if Tanks now tested	Scuppers	Masts, Yards, &c
Coamings	Bulkheads	Cargo Hatchways	Condition, how ascertained
Beams & Fastenings	Ceiling	Hatches	(State if wedges removed)
Outside Plating	Cement or Asphalt	Planking of Wood Vessels	Sails
Caulking of ditto	(State which.)	Caulking ditto	Equipment letter
Rivets	Rudder	Treenails ditto	Anchors, No. of
Breasthooks & Crutches	Steering gear and its connections	Breasthooks & Stemson ditto	Cables (State if now ranged)
Transoms	Windlass	Transoms, Pointers, & Crutches ditto	length size
Frames	Have Pumps now been examined and found efficient?	Timbers of Frame at openings ditto	(on board)
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Ditto ditto at other places ditto	Rule length size
Floors	Have Watertight Doors now been examined and found efficient?	Stringers, Clamps & Shelves ditto	Hawser & Warps
Keelsons		Salting ditto	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Survey Fee (per Section 28)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute New York SEP 13 1921
Character Assigned Withdraw class & insert (...)

Surveyor to Lloyd's Register of Shipping.
General Committee
Thursday 6th October 1921
American Committee's
decision confirmed
Lloyd's Register
Foundation
Dr. Nylk 7/10/21

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent her, or when will it be sent?

DISCLOSED SECTION

140

In Certificate required? If so, to be sent to

005443-005460-0631