

File -
B-619

Nov. 28/19.

SKINNER & EDDY CORPORATION
GE REQ. Pt-39691 HULL "C"

Mr. E. M. Salmon,
Lloyds Register of Shipping,
17 Battery Place,
New York, N.Y.

Dear Sir:-

In further reference to our discussion of the top half exhaust casing for the turbine for Skinner & Eddy Corp., Hull "C", please be advised that we wired Skinner & Eddy in regard to our having patched this casing advising them that you had rejected it on the basis of this patch work, but that you would permit us to use the casing if Skinner & Eddy agreed to the patch and to the subsequent replacement of this part in case of failure. They have replied to us as follows thru our Portland Office:

"Skinner & Eddy Contract GE-35333 Your telegram 20th On account of the fact that ship will be launched Dec. 20th the possible delay furnishing new casting customer agrees to accept exhaust casing with the distinct understanding that the above is the result of chaplet and is not a cold shot in casting itself and will expect us to renew casting in the future if any time it should fail from this cause Assuming patch is in upper half of casting Telegraph if this is the case and assure that this defect is not the result of a cold shot."

To which we replied as follows:

"Your night letter 20th Skinner & Eddy contract 35333 assure Skinner patched exhaust casing is result of chaplet and not cold shot in casting itself. Patch is also in upper portion of casing. Lloyds and American Bureau have accepted casing on this basis and we agree to renew casing at any time same might fail on account of patch."

We have since received telegram from Mr. H.C. Seaborn Vice-President and General Manager of the Skinner & Eddy Corporation asking us to further anticipate the shipping date which we have made. On the basis of this advice from Skinner & Eddy and our

© 2021
Lloyds Register
Foundation
1/2
005943-005960-0049

Mr. E. M. Salmon

-2-

understanding with you of November 19th we would be pleased to have you rescind the rejection of this casting.

Yours very truly,

E. B. WILLIAMS

TURBINE ENGINEERING DEPT.

EDW:MAM

J. Robinson
D.L. Boyle
W.B. Nicklas

J.R. 4/12/19



© 2021

Lloyd's Register
005443-05960-0049
Foundation