

2.

who had the cases before them on Friday, 18th instant, decided to give instructions for the class of each vessel to be withdrawn from the Society's Register Book and three dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

CHIEF SURVEYOR AND CHIEF ENGINEER SURVEYOR.

It is the duty of the Surveyors to see that the vessels are in every way fit to receive and carry passengers and cargo, and that the crew are all the while fit to be employed in the service.

S.S. No 2

24th November, 1921.

BS due 7.21

The boiler survey became due on 7.21. no part has been held.

The Owners requested that the classification of the vessel be discontinued on the expiration of the existing certificate.

It is submitted that the vessel class be withdrawn from the Register Book and three dots inserted in lieu thereof indicating that the class has been withdrawn at the Owners request.

Withdraw class
Insert ...

17
Amal
JWD
3/11/21



© 2021

Lloyd's Register
Foundation

005443-005460 006262