

1

Sent to Chief Surveyors 6.11.18

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Y/S "Governor John Lind" Report S. D. No. 5850**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.02.)

Nature of Survey \_\_\_\_\_ When due \_\_\_\_\_

The hand pumps & Kedge Anchor have been disensed with, as a War Emergency measure, at Owners request.

It is concluded the Owners are agreeable to supply these at the termination of the War, if requested to do so.

❖ 100A.1. (Steel)

10X (Steel)

Ceil. DB 248' 5646 F.P.T. 936. A.P.T. 886

FK. 5BH: pt. Cem. at P. P 33. 1349' F 36'



© 2020

Lloyd's Register  
Foundation